



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section																	
Water System Name		City of Mascoutah			System ID Number:		IL1630800		Current Inventory Date:		4/12/2024						
*Please enter totals in the empty box next to each category		Total Service lines:	3814	Total Lead:	7	Total Non-Lead:	3804	Total Galvanized Requiring replacement:	3	Total Unknown:	0	Website link to Material Inventory:		https://www.mascoutah.org/water-and-sewer			
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
		EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities If address is not a lead and copper sample site mark "N/A"	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc.	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (D) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (D) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (D) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (D) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
12 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
14 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
16 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
18 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
20 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
101 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
105 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
203 N 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N	
208 N 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N	
504 N 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
505 N 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
607 N 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
612 N 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
707 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
717 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
723 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
805 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
809 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
811 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
901 N 10TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
143 S 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
149 S 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
155 S 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
161 S 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
201 S 10TH ST	N/A	Y	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
201 S 10TH ST	N/A	Y	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
511 S 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
511 S 10TH ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N	
11 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
212 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
301 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
314 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
315 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
401 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
415 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
502 N 1ST ST	N/A	Y	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
508 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
601 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
602 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
603 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
611 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
612 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
613 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
614 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
616 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
704 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
705 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	
710 N 1ST ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N	

337 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
339 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
342 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
343 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
347 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
351 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
354 S 5TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
6TH & PARK DR	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
40 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
202 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
205 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
210 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
302 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
305 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
308 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
311 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
314 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
319 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
326 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
402 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
410 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
533 N 6TH ST	N/A	N	N			VISUAL INSPECTION	D	D	D	N/L	N	N/R	N				N			
846 N 6TH ST	N/A	N	N			VISUAL INSPECTION	D	D	D	N/L	N	N/R	N				N			
846 N 6TH ST	N/A	N	N			VISUAL INSPECTION	D	D	D	N/L	N	N/R	N				N			
846 N 6TH ST	N/A	N	N			VISUAL INSPECTION	D	D	D	N/L	N	N/R	N				N			
846 N 6TH ST	N/A	N	N			VISUAL INSPECTION	D	D	D	N/L	N	N/R	N				N			
846 N 6TH ST	N/A	N	N			VISUAL INSPECTION	D	D	D	N/L	N	N/R	N				N			
901 N 6TH ST POOL	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
973 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1038 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1180 N 6TH ST #3	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1180 N 6TH ST #4	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1190 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1358 N 6TH ST	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1358 N 6TH ST - BUSINESS	N/A	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			

1228 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
1229 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
1232 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1233 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1236 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1237 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1240 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1241 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1244 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1245 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1248 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1249 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1252 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1253 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1256 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1257 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1260 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1261 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1264 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
1265 ANTIQUE LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
105 ARBOR GLEN LN	N/A	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
201 ARBOR GLEN LN	N/A	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N			N			
11 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
12 N AUGUST ST A	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
12 N AUGUST ST B	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
110 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
111 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
114 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
201 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
202 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
205 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
209 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
210 N AUGUST ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N			N			
212 N AUGUST ST	N/A	N	N																		

1516 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1517 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1520 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1521 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1524 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1525 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1528 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1529 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1532 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1533 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1536 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1537 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1540 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1541 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1545 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1549 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1553 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1557 AUTUMN LAKES LANE	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
707 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	P	P	NL	N	N/R	N				N			
708 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
713 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
714 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
719 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
725 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
731 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
737 BEEBE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	NL	N	N/R	N				N			
1100 BEECHCRAFT BLVD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1101 BEECHCRAFT BLVD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1104 BEECHCRAFT BLVD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1105 BEECHCRAFT BLVD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1108 BEECHCRAFT BLVD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N				N			
1109 BEECHCRAFT BLVD	N/A	N	N	N																		

9239 BELLER DR B	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9237 BELLER DR A	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9237 BELLER DR B	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9241 BELLER DR A	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9241 BELLER DR SUITE B	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1000 BENELLI ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1004 BENELLI ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1008 BENELLI ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1012 BENELLI ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1016 BENELLI ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1020 BENELLI ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
901 BERETTA ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
905 BERETTA ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
15 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
119 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
200 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
201 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
204 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
205 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
208 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
211 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
212 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
215 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
301 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
302 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
305 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
309 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
315 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
412 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
523 N BERNARD ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
16 S BERNARD ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
200 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
208 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
209 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
300 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
301 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
305 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
306 BISCAYNE DR	N/A	N	N			VISUAL INSPECTION	C	C	C									

18 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
19 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
20 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
25 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
26 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
31 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
32 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
37 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
38 CHERYL DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
504 CHEVELLE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
505 CHEVELLE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
900 CHICKASAW CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
904 CHICKASAW CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
905 CHICKASAW CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
908 CHICKASAW CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
909 CHICKASAW CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
7 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
11 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
105 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
107 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
111 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
121 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
216 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
219 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
303 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
311 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
320 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
321 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
322 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
419 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
507 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
515 E CHURCH ST	N/A	N	N	N			VISUAL INSPECTION	P															

706 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
701 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
711 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
715 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
717 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
720 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
721 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
800 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
803 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
809 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
816 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
817 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
821 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
903 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
912 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
913 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
919 W CHURCH ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
922 W CHURCH ST #1	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #10	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #11	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #12	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #13	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #14	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #15	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #16	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #2	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #3	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #5	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #6	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #7	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #8	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST #9	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
922 W CHURCH ST APT 4	N/A																					

805 DOLT CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
103 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
109 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
115 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
121 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
127 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
133 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
202 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
208 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
214 CONCORD CIRCLE	LP1A006	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
220 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
226 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
1601 CONCORD CIRCLE	LP1A028	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
1602 CONCORD CIRCLE	LP1A026	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
1610 CONCORD CIRCLE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
1611 CONCORD CIRCLE	LP1A007	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N			
100 COPPER OAKS CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
CORRINGTON PLACE ENTRANCE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1 CORRINGTON PLACE A	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
2 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
3 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
4 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
5 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
6 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
7 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
8 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
9 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
10 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
11 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
12 CORRINGTON PLACE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
416 E CORRINGTON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
417 E CORRINGTON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
503 E CORRINGTON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
900 W CORRINGTON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
901 W CORRINGTON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
905 W CORRINGTON ST	N/A	N	N			VIS														

402 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
408 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
408 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
414 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
416 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
418 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
420 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1000 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1060 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1112 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1115 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1217 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1241 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1243 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1247 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1325 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1337 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1339 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1341 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1359 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1420 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1535 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1541 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1545 N COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
23 S COUNTY RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #1	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #10	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #11	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #12	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #13	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #14	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #15	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #16	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
31 S COUNTY RD #17	N/A	N	N	N			VISUAL INSPECTION	C	C	C											

706 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
707 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
712 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
713 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
719 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
726 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
727 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
732 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
738 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
800 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
806 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
812 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
818 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
900 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
906 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
909 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
915 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
918 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
921 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
924 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
927 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
930 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
933 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
936 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
939 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
942 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
945 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
948 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
954 DERE BERE DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
620 DONAPHAN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
513 E DONAPHAN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
280 DOUGLAS AVE APT 1	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
280 DOUGLAS AVE APT 10	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
280 DOUGLAS AVE APT 11	N/A	N	N	N			VISUAL INSPECTION														

291 DOUGLAS AVE APT 11	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 12	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 13	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 14	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 15	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 16	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 2	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 3	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 4	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 5	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 6	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 7	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 8	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
291 DOUGLAS AVE APT 9	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
344 DOUGLAS AVE #1	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
344 DOUGLAS AVE #3	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
344 DOUGLAS AVE #4	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
344 DOUGLAS AVE B	N/A	N	N		VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
366 DOUGLAS AVE #1	N/A	N	N		VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
366 DOUGLAS AVE #2	N/A	N	N		VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
366 DOUGLAS AVE #3	N/A	N	N		VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
366 DOUGLAS AVE #4	N/A	N	N		VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
389 DOUGLAS AVE #1	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
389 DOUGLAS AVE #2	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
389 DOUGLAS AVE #3	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
389 DOUGLAS AVE #4	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
391 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
392 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
396 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
397 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
402 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
403 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
408 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
409 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
414 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
415 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
418 DOUGLAS AVE	N/A	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N						

504 ELM ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
506 ELM ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1201 ETUNG DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
501 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
505 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
509 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
513 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
517 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
521 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
601 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
605 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
609 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
612 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
613 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
616 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
617 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
620 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
621 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
624 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
625 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
628 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
629 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
632 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
633 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
636 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
637 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
640 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
641 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
644 FALLEN TIMBER LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
100 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
104 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
108 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
112 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
116 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
119 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
120 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N		</				

[illegible]

556 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
559 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
560 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
564 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
568 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
600 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
604 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
608 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
612 FALLING LEAF WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
107 FILMORE ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
212 FILMORE ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
209 E FILMORE ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT A	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT B	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT C	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT D	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT E	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT F	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT G	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
700 FOUNTAIN VIEW DR APT H	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT A	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT B	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT C	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT D	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT E	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT F	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT G	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 FOUNTAIN VIEW DR APT H	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT A	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT B	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT C	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT D	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT E	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT F	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT G	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 FOUNTAIN VIEW DR APT H	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N								

5 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
6 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
7 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
8 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
10 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
12 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1128 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1131 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1132 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1135 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1136 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1139 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1140 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1143 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1144 FOX RUN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1001 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9613 FUESSER RD A	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9631 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9711 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9810 FUESSER RD	N/A	Y	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9814 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9910 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9914 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9918 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9922 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	P	N/L	N	N/R	N				N			
10017 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
10025 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	P	N/L	N	N/R	N				N			
10033 FUESSER RD	N/A	N	N	N			VISUAL INSPECTION	C	C	P	N/L	N	N/R	N				N			
10 E GEORGE ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
17 E GEORGE ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
20 E GEORGE ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
24 E GEORGE ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
100 E GEORGE ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			

313 GRANT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
309 GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
317 GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
320 GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
330 GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
314 N GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
315 N GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
321 N GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
325 N GRANT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
6 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
12 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
16 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
20 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
109 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
114 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
117 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
200 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
201 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
214 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
306 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
312 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
316 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
506 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
512 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
515 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
516 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
602 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
612 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
618 E GREEN ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N	N				N			
1 W GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
5 W GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N	N				N			
9 W GREEN ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C												

918 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
901 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
901 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
914 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
915 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
919 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
922 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
925 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
926 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
932 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
935 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
936 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1004 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1005 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1009 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1013 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1017 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1018 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1025 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1029 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1033 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1034 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1037 W GREEN ST	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
59 W GREEN ST A	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1101 GULFSTREAM WAY	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1104 GULFSTREAM WAY	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1105 GULFSTREAM WAY	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1108 GULFSTREAM WAY	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1112 GULFSTREAM WAY	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1116 GULFSTREAM WAY	N/A	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R										

84 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
90 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
91 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
97 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
102 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
108 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
421 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
720 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
820 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
900 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
906 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
910 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
916 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
920 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
922 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1001 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
1010 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1011 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1017 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1023 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1029 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1035 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1041 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1047 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1101 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1111 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1203 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1204 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1205 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1207 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
1212 W HARNETT ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
9663 HAYDEN DR APT 1	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
9663 HAYDEN DR APT 2	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
9663 HAYDEN DR APT 3	N/A	N	N	N																	

9679 HAYDEN DR APT 2	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9679 HAYDEN DR APT 3	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9679 HAYDEN DR APT 4	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9679 HAYDEN DR APT 5	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9679 HAYDEN DR APT 6	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9679 HAYDEN DR APT 7	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9679 HAYDEN DR APT 8	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 1	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 2	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 3	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 4	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 5	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 6	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 7	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9680 HAYDEN DR APT 8	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9730 HAYDEN DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
9785 HAYDEN DR SUITE A	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
9785 HAYDEN DR SUITE B	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
200 HOD CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
201 HOD CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
205 HOD CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	N/L	N	N/R	N				N			
1 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
2 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
3 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
4 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
5 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
6 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
7 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
8 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
100 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1000 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1004 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1005 HUNTERS TRAIL	N/A	N	N	N			VISUAL INSPECTION	C	C	C	N/L	N	N/R	N				N			
1008 HUNTERS TRAIL	N/A																				

305 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
308 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
315 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
316 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
317 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
322 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
323 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
402 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
403 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
418 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
422 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
502 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
506 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
512 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
515 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
517 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
519 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
520 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
521 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
523 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
600 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
610 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
704 N INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
15 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
101 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
102 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
110 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
202 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
207 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
210 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
300 S INDEPENDENCE ST #40	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
407 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
409 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
414 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
417 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
418 S INDEPENDENCE ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N</		

1000 INDIAN PRAIRIE DR	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1004 INDIAN PRAIRIE DR	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1008 INDIAN PRAIRIE DR	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1012 INDIAN PRAIRIE DR	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
602 INDUSTRIAL ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
634 INDUSTRIAL ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
620 INDUSTRIAL ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
9703 IROQUOIS DR	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
9711 IROQUOIS DR	N/A	N	Y	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
9719 IROQUOIS DR	N/A	N	Y	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
204 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
205 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
210 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
211 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
214 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
215 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
216 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
310 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
315 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
316 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
322 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
323 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
330 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
333 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
339 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
406 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
407 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
410 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
414 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
417 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
419 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
420 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
425 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
426 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
430 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
431 N JACKSON ST	N/A	N	N	N		VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		

517 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
518 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
520 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
600 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
603 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
603 N JEFFERSON ST - A	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
608 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
611 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
705 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
710 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
714 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
721 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
722 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
739 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
751 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
759 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
780 N JEFFERSON ST	N/A	Y	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
832 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
844 N JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
9 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
100 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
112 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
206 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
208 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
212 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
215 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
215 S JEFFERSON ST - A	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
302 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
308 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
312 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
404 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
408 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
413 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
502 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
506 S JEFFERSON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		

318 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
320 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
321 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
401 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
404 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
414 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
417 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
500 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
506 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
507 N JOHN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
508 N JOHN ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
102 S JOHN ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
104 S JOHN ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
110 S JOHN ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
111 S JOHN ST HOUSE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
112 S JOHN ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
607 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
608 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
613 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
614 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
619 JOSEPH DR	LP1A015	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
620 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
625 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
626 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
631 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
632 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
638 JOSEPH DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
1002 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1003 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1006 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1007 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1010 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1011 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1015 KANKAKEE TRAIL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
203 KIILN CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
206 KIILN CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
9607 KLINGS CT	N/A	N	N			VISUAL INSPECTION	P</												

1607 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1608 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1613 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1614 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1619 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1620 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1625 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1626 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
1631 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1632 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	N/L	N	N/R	N					N				
1638 LANDMARK DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	P	N/L	N	N/R	N					N				
1158 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1159 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1162 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1163 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1167 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1170 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1171 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1174 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1175 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1178 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1179 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1182 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1183 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1186 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1187 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1190 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1191 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1194 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
1195 LARKSPUR DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				

[illegible]

1457 LEXI LN	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1461 LEXI LN	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1465 LEXI LANE	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1502 LEXI LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1508 LEXI LANE	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1519 LEXI LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1524 LEXI LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1535 LEXI LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1539 LEXI LN	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1543 LEXI LN	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1551 LEXI LANE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1469 LEXI LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1511 LEXI LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1527 LEXI LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1214 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1226 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1230 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1236 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1246 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1255 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1256 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1259 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1260 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1268 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1269 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1321 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1326 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1329 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1330 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1334 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1338 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1407 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1419 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1420 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1437 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1501 LINCOLN BLVD	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		

9733 LUAN DR APT 6	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9733 LUAN DR APT 7	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9733 LUAN DR APT 8	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 1	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 2	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 3	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 4	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 5	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 6	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 7	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
9741 LUAN DR APT 8	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
904 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
911 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
915 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1001 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1012 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1015 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1016 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1020 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1021 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1024 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1028 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1031 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1032 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1105 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
1205 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N					N			
1221 MADISON ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	C	NL	N	N/R	N					N			
808 W MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
912 W MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			
916 W MADISON ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	P	NL	N	N/R	N					N			

217 E MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
219 E MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N		N/R	
223 E MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
227 E MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
302 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
303 E MAIN ST MOTO MART	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
308 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
312 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
312 E MAIN ST REAR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
320 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
323 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
402 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
406 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
410 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
414 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
418 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
422 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
422 E MAIN ST APT A	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
500 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST APT 2 & 10 WATER	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST LAUNDRY ROOM	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #1	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #10	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #11	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #2	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #3	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #4	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #5	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #6	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #7	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #8	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
507 E MAIN ST #9	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
510 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
514 E MAIN ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			

48 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
52 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
58 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
60 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
63 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
101 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
101 W MAIN ST - A	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
102 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
112 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
121 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
126 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
134 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
134 W MAIN ST - A	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
134 W MAIN ST - B	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
135 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
204 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
205 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N				
215 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
220 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
220 W MAIN ST-FRONT	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
305 W MAIN ST	LA3C060	N	Y					VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
306 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
311 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
314 W MAIN ST	N/A	N	N	Y				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #10	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #11	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #12	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #14	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #20	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #21	N/A	N	N	N				VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N				
315 W MAIN ST #31	N/A	N	N	N				VISUAL INS																

802 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
805 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
808 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
811 W MAIN ST	LP1CD21	N	Y			VISUAL INSPECTION	P	P	L	L	N	N/R	N				N		
812 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
816 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
900 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
901 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
904 W MAIN ST	LP1CD65	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
908 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
911 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
912 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
913 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
915 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
917 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
919 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
922 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
927 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
929 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
931 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
933 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1004 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1005 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1008 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1009 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1012 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1016 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1017 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1025 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1027 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1034 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1035 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1040 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1043 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1100 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1103 W MAIN ST	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1107 W MAIN ST	N/A	N	Y																

9600 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9601 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9604 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9607 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9608 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9611 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9615 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9616 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9619 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9620 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9623 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9624 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9627 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9628 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9632 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9636 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9640 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9641 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9648 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9652 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9656 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9664 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9669 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9673 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9676 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9680 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9684 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9687 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9688 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9702 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
9706 MALLARD DR	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
201 MAPLE ST	N/A	N	N	N	N	VISUAL INSPECTION	P	P	P	NL	N	N/R	N	N				N			
203 S MAPLE ST	N/A	N	N	N	N	VISUAL INSPECTION	C	C	C	NL	N	N/R	N	N				N			
2																					

105 MASCOUTAH PLAZA DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
112 MASCOUTAH PLAZA DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
205 MASON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
208 MASON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
209 MASON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
212 MASON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1205 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1208 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1212 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1215 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1220 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1221 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1224 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1225 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1228 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1229 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1233 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1415 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1420 MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1232 W MCKINLEY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1107 MENOMINEE TRL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1113 MENOMINEE TRL	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1121 MENOMINEE TRL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1133 MENOMINEE TRL	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1137 MENOMINEE TRL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1140 MENOMINEE TRL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1152 MENOMINEE TRL	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1153 MENOMINEE TRL	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
3 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
4 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
9 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
10 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
15 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
16 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
21 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
22 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
27 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
28 MICHELLE DR	N/A	N	N			VISUAL INSPECTION	C</											

[illegible]

1887 NATHAN AVE #1	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1887 NATHAN AVE #2	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1887 NATHAN AVE #3	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1887 NATHAN AVE #4	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1963 NATHAN AVE APT A	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1963 NATHAN AVE APT B	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1963 NATHAN AVE APT C	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1963 NATHAN AVE APT D	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1975 NATHAN AVE #1	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1975 NATHAN AVE #2	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1975 NATHAN AVE #3	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1975 NATHAN AVE #4	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1986 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1987 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
2063 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
2072 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
2075 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
2087 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
2163 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
2174 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
2175 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
2186 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N				N		
2187 NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1888 N NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1886 S NATHAN AVE	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
3 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
9 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
23 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
100 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
103 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
105 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
109 E OAK ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
309 E OAK ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
600 E OAK ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
603 E OAK ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
608 E OAK ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		

403 OPAL CT	N/A	N	N	N					VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
406 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
407 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
410 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
411 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
414 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
415 OPAL CT	N/A	N	N	N	N/A				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
418 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
419 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
423 OPAL CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
900 OTTAWA CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
901 OTTAWA CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
904 OTTAWA CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
905 OTTAWA CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
908 OTTAWA CT	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
905 PARK DR	N/A	N	N	N	N				VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
222 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
222 E PATTERSON ST #1	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
222 E PATTERSON ST #2	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
318 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
409 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
415 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
421 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
502 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
512 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
515 E PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	P	P	P	P	N/L	N	N/R	N					N				
3 W PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
6 W PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	C	C	C	C	N/L	N	N/R	N					N				
9 W PATTERSON ST	N/A	N	N	N	N				VISUAL INSPECTION	C	C	C	C	N/L</												

201 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
202 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
207 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
212 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
213 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
219 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
225 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
226 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
231 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
232 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
237 PERROTTET DR	N/A	N	N			VISUAL INSPECTION	C	C	P	NL	N	N/R	N					N			
1 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
2 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
3 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
4 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
5 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
6 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
7 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
9617 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9620 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9621 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9624 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9625 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9629 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9632 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9633 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9637 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
9640 PHEASANT BEND	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					N			
102 E PHILLIPS ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
106 E PHILLIPS ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
112 E PHILLIPS ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
119 E PHILLIPS ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
120 E PHILLIPS ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N					N			
202 E PHILLIPS ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N	</							

16 E POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
320 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
535 E POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
606 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
607 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
608 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
609 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
612 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
613 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
619 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
620 E POPLAR ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
3 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
4 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
5 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
13 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
16 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
17 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
25 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
28 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
34 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
35 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
40 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
43 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
47 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
48 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
54 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
60 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
105 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
110 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
111 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
113 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
115 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
117 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
120 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
128 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
132 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
133 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
202 W POPLAR ST	N/A	N	Y			VISUAL INSPECTION	C</											

1011 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1012 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1015 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1016 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1019 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1020 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1023 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1024 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1027 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1028 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1032 W POPLAR ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
12 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
14 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
16 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
18 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
20 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
22 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
24 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
26 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
28 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
31 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
33 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
35 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1125 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1126 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1129 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1130 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1134 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1138 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1139 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
1142 QUAIL POINT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
9650 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9651 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9654 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9655 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9658 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9663 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9667 QUAPAW CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N					

425 S RAILWAY ST	LP1C048	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
428 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
432 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
433 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
436 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
439 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
440 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
444 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
445 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
449 S RAILWAY ST	LP1C037	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
450 S RAILWAY ST APT A	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
450 S RAILWAY ST APT B	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
450 S RAILWAY ST APT C	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
450 S RAILWAY ST APT D	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
450 S RAILWAY ST APT E	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
457 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
502 S RAILWAY ST B	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
505 S RAILWAY ST 100	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
508 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
509 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
513 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
517 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
521 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
555 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
559 S RAILWAY ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
550 REDSTONE CT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
551 REDSTONE CT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
554 REDSTONE CT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
555 REDSTONE CT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
558 REDSTONE CT	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N				N		
561 REDSTONE CT	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1001 REMINGTON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1004 REMINGTON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1005 REMINGTON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1008 REMINGTON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1009 REMINGTON ST	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1012 REMINGTON ST																			

18 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
18 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
24 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
102 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
112 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
113 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
120 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
123 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
209 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
212 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
213 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
219 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
220 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
221 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
309 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
316 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
321 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
322 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
402 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
409 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
500 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
505 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
511 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
511 E SOUTH ST #9	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
600 E SOUTH ST #11	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
600 E SOUTH ST #1	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
600 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
600 E SOUTH ST #5	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
608 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
610 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
614 E SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N			
615 E SOUTH ST #2	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
615 E SOUTH ST #21	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			
615 E SOUTH ST #22	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N			

617 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
620 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
621 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
701 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
704 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
707 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
712 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
714 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
719 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
720 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
800 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
801 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
808 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
809 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
810 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
812 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
815 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
816 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	G	NL	N	N/R	N				N		
820 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	G	NL	Y	N/R	N				N		
821 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	Y	N/R	N				N		
824 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
902 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
905 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
907 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
910 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
920 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
921 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
923 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
929 W SOUTH ST	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
101 ST CHRISTOPHER CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
102 ST CHRISTOPHER CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
105 ST CHRISTOPHER CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
106 ST CHRISTOPHER CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
109 ST CHRISTOPHER CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
110 ST CHRISTOPHER CT	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
114 ST CHRISTOPHER CT	N/A																			

935 W STATE ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
937 W STATE ST A	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
517 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
521 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
525 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
528 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
529 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
533 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
536 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N		
537 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N		
540 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N		
541 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N			N		
544 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
545 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
548 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
549 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
552 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
553 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
556 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
557 STREAMSTONE LN	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
400 SUMMIT OAKS CIRCLE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
401 SUMMIT OAKS CIRCLE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
404 SUMMIT OAKS CIRCLE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
405 SUMMIT OAKS CIRCLE	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
800 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
801 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
804 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
805 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
808 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
809 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
812 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
813 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
817 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
821 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
826 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
829 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
832 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
833 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
836 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
837 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
841 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
845 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
849 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
853 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
857 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
861 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
865 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
869 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
873 TANZANITE LN	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9624 TEAL CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9625 TEAL CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9628 TEAL CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9629 TEAL CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9632 TEAL CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9633 TEAL CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1305 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1400 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1404 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1405 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1408 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1409 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1412 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1413 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1416 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1417 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1420 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1421 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1500 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1504 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1505 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1508 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1509 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1512 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1516 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1520 TIMBERBROOK DR	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
776 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
777 TOPAZ CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
781 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
784 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
788 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		

789 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
792 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
793 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
796 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
797 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
801 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
806 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
807 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
810 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
811 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
817 TOPAZ CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
821 TOPAZ CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
826 TOPAZ CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
827 TOPAZ CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
830 TOPAZ CT	N/A	N	Y			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
831 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
836 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
840 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
844 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
846 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
848 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
850 TOPAZ CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
402 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
403 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
406 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
407 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
410 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
411 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
414 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
415 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
418 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
419 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
423 TURQUOISE CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
40 W UNION ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
40 W UNION ST - B	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
40 W UNION ST A	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
40 W UNION ST WATER SHED	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		
56 W UNION ST	N/A	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N			N		

301 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
305 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
401 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
405 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
409 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
501 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
505 WHETSTONE LN	N/A	N	N	N/A			VISUAL INSPECTION	P	P	C	NL	N	N/R	N				N		
509 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	P	P	C	NL	N	N/R	N				N		
513 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
601 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
605 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
609 WHETSTONE LN	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1126 WHIMBREL RUN	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1130 WHIMBREL RUN	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1134 WHIMBREL RUN	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1138 WHIMBREL RUN	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1142 WHIMBREL RUN	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1146 WHIMBREL RUN	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
205 WHITE LILAC CT	N/A	N	Y				VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1128 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1131 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1132 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1135 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1136 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1139 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1140 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1143 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1144 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1148 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	C	C	C	NL	N	N/R	N				N		
1151 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1152 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1160 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1164 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1168 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N				N		
1169 WIDGEON DR	N/A	N	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R							

[illegible]

9718 WINNEBAGO WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9721 WINNEBAGO WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
9722 WINNEBAGO WAY	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1002 WYANDOT CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1006 WYANDOT CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		
1007 WYANDOT CT	N/A	N	N			VISUAL INSPECTION	P	P	P	NL	N	N/R	N			N		